



cc: Adm
10/11/16
SA

State of New Jersey

DEPARTMENT OF ENVIRONMENTAL PROTECTION
ENGINEERING & CONSTRUCTION
DIVISION OF DAM SAFETY & FLOOD CONTROL
Mail Code 501-01A

BOB MARTIN
Commissioner


CHRIS CHRISTIE
Governor

KIM GUADAGNO
Lt. Governor

PO Box 420, Trenton, NJ 08625-0420
Telephone: 609-984-0859 Fax: 609-984-1908

Ironbound Real Estate Holdings, LLC
113 Greenwich Street
Belvidere, New Jersey 07823

Re: Mine Hill Reservoir Dam (NJDEP File No. 24-23)
Mount Olive Township, Morris County



Dear Dam Owner/Operator:

This is in reference to the revised 2016 Inspection Report prepared on your behalf by Mary L. Paist-Goldman, P.E., of Princeton Hydro, and submitted under an August 30, 2016 cover letter.

Based upon a review of the above-referenced report, Mine Hill Reservoir Dam was found by your engineer to be in FAIR condition with maintenance, repairs and studies necessary. Per the New Jersey Dam Safety Standards (N.J.A.C. 7:20-1.11), the next regular inspection of the dam is to be performed by **April 8, 2018**.

The included Dam Safety Compliance Schedule was determined to be acceptable by the Bureau of Dam Safety (Bureau). Per the schedule, general maintenance is to be completed by **December 31, 2016** and per the cover letter, a permit application for either removal or rehabilitation of the dam is to be submitted by **August 31, 2017**.

It was noted in the above-referenced report that an updated Emergency Action Plan (EAP) notification flowchart was to be included but was not provided. Additionally, the EAP on file with the Bureau dates back to the original EAP dated November 1991. Therefore, an updated EAP must be provided to the Bureau for review by **December 31, 2016**.

Should you have any questions regarding this matter, please contact Marcus L. Roorda of this office at (609) 984-0859.

Sincerely,

John H. Moyle, P.E., Director
Division of Dam Safety and Flood Control

C: Mary L. Paist-Goldman, P.E., Princeton Hydro
Mount Olive Township Engineer & Clerk
Morris County Engineer

V:\nhf\bdscf\DSS\DATABASE\16letter\24023MLR16a.docx